Headset Connection Cord, and Extension Cord Jacket Specifications

Connection Cord	Specifications	
SEDFLEX Jacket:	Temperature Range	-40° to 60° C
	Abrasion Resistance	Good
	Flexibility at Low Temperature	Good
	Minimum Melting Temperature	105° C
	Chemical Resistance	Excellent particularly to Gasoline, ethanol, methanol, motor oil, salt solutions.
	Surface Finish	Smooth, easy to clean
Vinyl (PVC) Jacket:	Temperature Range	-10° to 60° C
	Abrasion Resistance	Fair
	Flexibility at Low Temperature	Poor
	Chemical Resistance	Good
	Surface Finish	Clean, decontaminate
Neoprene Jacket:	Temperature Range	-20° to 90° C
	Abrasion Resistance	Good
	Flexibility at Low Temperature	Good
	Chemical Resistance	Fair
	Surface Finish	Difficult to clean
Silicone Rubber Jacket:	Temperature Range	-70° to 150° C
	Abrasion Resistance	Excellent
	Flexibility at Low Temperature	Excellent
	Chemical Resistance	Excellent
	Surface Finish	Easy to clean and decontaminate